

TT40 incident at 23:46 on 25th October 2004

J. Wenninger AB-OP


- The incident : cause and consequences.
- Direct 'follow up' actions.
- Lessons for the future.

With input from many colleagues of the AB department, in particular
B. Balhan, E. Carlier, B. Goddard, M. Jonker, V. Mertens, R. Schmidt,
J. Uythoven

What happened ?


- During a high intensity extraction test, a LHC beam with 3.2×10^{13} protons (nominal LHC injection) impacted in the second quadrupole of the TT40 transfer line to LHC and CNGS following a PC fault on the extraction septum magnet.
- The magnet had to be replaced 1 week later : ~ 24 hours downtime for SPS and obviously some dose to the personnel (mainly vacuum and magnet group).
- The vacuum chamber of the quadrupole was ripped open.
- The quadrupole coil may be damaged (tbc).
- We learned a lesson and many people woke up and realized what high intensity beams are !

(Future) SPS extractions



Extraction channel

- Extraction bumpers (= strong & fast orbit correctors, 4 / plane) :
→ 35 mm amplitude horizontal bump @ beam position monitor.
- Extraction kicker MKE (5 magnets, 0.53 mrad).
- Magnetic septum MSE (6 magnets, 22000 A, 12 mrad) :
This magnet has a very short time constant of 23 ms !



(Very) few words on interlocks

- The TT40/TI8 lines are equipped with a beam interlock system that is essentially identical to the future LHC beam interlock system.
- The interlock system was fully operational during the test.
- For the power converter surveillance :
 - The current of the PCs was surveyed a few ms before extraction. No extraction permit was given if the current fell outside a tolerance.
 - The tolerance ranges (TT40 & TI8) :
 - 3×10^{-4} on main dipoles and quadrupoles (2 PCs).
 - $1-2 \times 10^{-3}$ on other magnets (26 PCs).
 - The average current over 10 ms was used for the interlocks :
 - The 'dead zone' where a problem (PC fault) could not be detected anymore was in the range 6 ms + delay from averaging.
 - For the extraction septum this interlock is not sufficient to ensure full safety because the time constant is too short. This fact was KNOWN. A solution to this problem is/was under development (also for the LHC).


Extraction septum in the SPS tunnel



Circulating beam

Extracted beam

Temperature sensor cables



First part of TT40 in the SPS tunnel


QTRF4002
beam impact



The damage on the vacuum chamber



Signs of heating over ~ 1 m



Chamber is cut over ~ 20 cm


Incident sequence

- Before the incident we observed PC faults on the MSE extraction septum correlated to unphysical temperature interlocks from the magnet.
- The magnet expert detected spurious beam induced interlocks due to Electro-Magnetic Coupling (EMC) of beam signals on temperature sensor cables (used for magnet protection).
- Since the interlocks were FAKE, the expert decided to disconnect the temperature sensors (there is a redundant protection over water T).
- The beam tests continued, and we were struck by another magnet interlock that was not understood at the time. This interlock fell exactly into our interlock system 'dead zone' !
- Further tests performed 2 weeks later showed that there was also EMC between the temperature sensors cables and an interlock signal cable on water valves that most likely caused the interlock → 'coupled' interlock.

Incident timing

- The **BLUE** curve is obtained from a PC simulation (PC off) by AB/PO.
- The timing of **PC current survey** (0.1 % tolerance) and of the precise **extraction time** is obtained from the Beam Interlock System logging.
- This reconstruction is consistent (within ~ 0.5 ms) with the beam impact point.

Magnetic septum current change



What is the probability for such an event ?

Naively :

- The dead-time of the surveillance is ~ 10 ms.
- The SPS cycle is 28.8 seconds long.

→ random fault probability ~ 3×10^{-4}

More realistic – with our test conditions :

- The faults were correlated to a high intensity beam with very short bunch length close to the MSE → faults occur mostly close to the extraction time !
- Therefore the fault occurs mostly in a time window of 100-1000 ms near extraction.

→ fault probability ~ 1-10% → rather 'likely' !

The lesson : beware of correlated 'faults' !

What when wrong...

- The MSE magnet interlock system was 'swamped' by beam induced EMC. The presence of EMC was KNOWN to BT experts – effects underestimated.
- We missed an important interlock. People in charge of interlocks were not informed about the PLC controlling the MSE magnet.
- Not enough BEAM time was devoted to interlock testing → might have tightened current surveillance and prevented incident.
- The high intensity extraction setting up was 'mixed' with the actual high intensity beam tests :
 - Led to time pressure, in particular because of other delays.
- The TI8 commissioning and TT40 high intensity were grouped into a continuous 72 hour period (high intensity at the end) :
 - No time to analyse 'quietly' the interlock system and its performance.
 - Many persons were needed throughout the period. Not ideal even if absence of rest was not in itself the triggering problem.
- There was no single person responsible for the tests and for safe operation.